



Product Discontinuance Notice (PDN)

Manufacturer:		For queries:	
RAYLASE GmbH Argelsrieder Feld 2+4 82234 Wessling Germany info@raylase.de www.raylase.de		Your customer number: Your contact person: Tel.: +49 8153 9999 699 E-mail: PDN@raylase.de	
		Date of publication:	31/07/2022
		PDN ID/version:	202204-01

Reason for discontinuance:

Due to ongoing supply problems of important components in the world market for the affected products by our suppliers, we are unfortunately forced to discontinue the product series and their articles listed below.

Discontinued product series and products			Replacement (100% compatibility is not guaranteed)	
Article no.	Description		Article no.	Description
SUPERSCAN III-10			Successor product	
M0000004274	SS-III-10 [TY]	SI-[W2]-ML-D2	SS-IV-10 [TY]	SI-[W]-VC-SX
M0000004277	SS-III-10 [TY]	SI-[W]-ML-D2	SS-IV-10 [TY]	SI-[W]-VC-SX
M0000004278	SS-III-10 [TY]	SI-[W]-MS-D2	no successor product	
M0000004280	SS-III-10 [DY]	SI-[W]-ML-D2	no successor product	
M0000004286	SS-III-10 [Y]	SI-[W]-ML-D2	SS-IV-10 [Y]	SI-[W]-VC-SX
M0000004287	SS-III-10 [Y]	SI-[W]-MS-D2	no successor product	
M0000004288	SS-III-10 [Y]	SI-[W]-MR-D2	SS-IV-10 [Y]	SI-[W]-M-SX
M0000004289	SS-III-10 [Y]	SI-[W2]-ML-D2	SS-IV-10 [Y]	SI-[W]-VC-SX
M0000004291	SS-III-10 [Y]	SI-[W2]-MR-D2	SS-IV-10 [Y]	SI-[W]-M-SX
M0000004575	SS-III-10 [TY]	SI-[W]-MS-D1	no successor product	
M0000004583	SS-III-10 [Y]	SI-[W]-ML-D1	SS-IV-10 [Y]	SI-[W]-VC-SX
M0000006606	SS-III-10 [DY]	SC-[W2]-ML-D2	no successor product	
M0000006609	SS-III-10 [DY]	SC-[W]-ML-D2	no successor product	
M0000006621	SS-III-10 [Y]	SC-[W]-ML-D2	no successor product	
M0000007604	SS-III-10 [1940]	SI-[W]-ML-D2	no successor product	

Discontinued product series and products			Replacement (100% compatibility is not guaranteed)	
Article no.	Description		Article no.	Description
SUPERSCAN III-15			Successor product	
M0000003787	SS-III-15 [TY]	QU-[W2]-ML-D2	SS-IV-15 [TY]	QU-[W2]-VC-SX
M0000003790	SS-III-15 [DY]	QU-[W2]-ML-D2	SS-IV-15 [DY]	QU-[W2]-VC-SX
M0000003793	SS-III-15 [780-980]	QU-[W2]-ML-D2	no successor product	
M0000003802	SS-III-15 [TY]	QU-[W]-ML-D2	SS-IV-15 [TY]	QU-[W]-VC-SX
M0000003844	SS-III-15 [TY]	SI-[W]-MR-D2	no successor product	
M0000003845	SS-III-15 [DY]	SI-[W]-ML-D2	no successor product	
M0000003847	SS-III-15 [DY]	SI-[W]-MR-D2	no successor product	
M0000003854	SS-III-15 [DY]	SI-[W2]-ML-D2	no successor product	
M0000003857	SS-III-15 [Y]	SI-[W2]-MR-D2	no successor product	
M0000003858	SS-III-15 [Y]	SI-[W2]-ML-D2	no successor product	
M0000003860	SS-III-15 [C]	SI-[W2]-MR-D2	no successor product	
M0000003862	SS-III-15 [C]	SI-[W2]-ML-D2	no successor product	
M0000004502	SS-III-15 [DY]	QU-[W2]-ML-D1	no successor product	
M0000004513	SS-III-15 [DY]	QU-[W]-MR-D1	no successor product	
M0000004538	SS-III-15 [TY]	SI-[W]-ML-D1	no successor product	
M0000004541	SS-III-15 [DY]	SI-[W]-ML-D1	no successor product	
M0000004553	SS-III-15 [Y]	SI-[W2]-MR-D1	no successor product	
M0000004558	SS-III-15 [C]	SI-[W2]-ML-D1	no successor product	
M0000005917	SS-III-15 [DY+Y]	QU-[W]-ML-D2	no successor product	
M0000005972	SS-III-15 [C]	SC-[W]-ML-D2	SS-IV-15 [C]	SC-[W]-VC-SX
M0000006220	SS-III-15 [AG]	QU-[W]-MS-D2	no successor product	
M0000007660	SS-III-15 [DY+Y]	QU-[W]-ML-D1	no successor product	
SUPERSCAN III-20			Successor product	
M0000005538	SS-III-20 [YIL]	QU-[W]-ML-D2	SS-IV-20 [YIL]	QU-[W]-VC-SX
M0000005549	SS-III-20 [C]	SI-[W2]-MR-D2	SS-IV-20 [C]	SI-[W]-VC-SX
M0000005556	SS-III-20 [Y]	SI-[W]-ML-D2	no successor product	
M0000005558	SS-III-20 [C]	SI-[W]-MR-D2	no successor product	
M0000005559	SS-III-20 [C]	SI-[W]-ML-D2	SS-IV-20 [C]	SI-[W]-VC-SX
M0000005588	SS-III-20 [TY]	QU-[WL]-MR-D1	no successor product	
M0000006681	SS-III-20 [C]	SC-[W]-ML-D2	SS-IV-20 [C]	SC-[W]-VC-SX
M0000007837	SS-III-20 [DY+Y]	QU-[W]-ML-D2	no successor product	
M0000009449	SS-III-20 [1020-1070]	SC-[W]-ML-D2	no successor product	

Discontinued product series and products			Replacement (100% compatibility is not guaranteed)	
Article no.	Description		Article no.	Description
SUPERSCAN III-30			Successor product	
M0000004935	SS-III-30 [Y]	SI-[WL]-ML-D1	SS-IV-30 [Y]	SI-[WL]-VC-SX
M0000004966	SS-III-30 [Y]	QU-[WL]-ML-D1	SS-IV-30 [Y]	QU-[WL]-VC-SX
M0000006036	SS-III-30 [1060-1080] V2	SC-[WA]-ML-D2	no successor product	
M0000006047	SS-III-30 [900-1100+AL] V2	SC-[W2]-ML-D2	SS-IV-30 [900-1100+AL] V2	SC-[W2]-VC-SX
M0000006050	SS-III-30 [900-1100+AL] V2	SC-[WA]-ML-D2	SS-IV-30 [900-1100+AL] V2	SC-[WA]-VC-SX
M0000006051	SS-III-30 [900-1100+AL] V2	SC-[WA]-MR-D2	no successor product	
M0000006075	SS-III-30 [C] V2	SC-[W2L]-ML-D1	SS-IV-30 [C] V2	SC-[W2L]-VC-SX
M0000006078	SS-III-30 [C] V2	SC-[WA]-ML-D2	no successor product	
M0000006349	SS-III-30 [1060-1080]	QU-[W2A]-ML-D2	SS-IV-30 [1060-1080] V3	QU-[W2A]-VC-SX
M0000006721	SS-III-30 [900-1100+AL]	QU-[W2A]-ML-D2	SS-IV-30 [900-1100+AL]	QU-[W2A]-VC-SX
M0000007021	SS-III-30 [1060-1080]	QU-[W2AL]-ML-D1	no successor product	
M0000007143	SS-III-30 [780-980+AL] V3	QU-[W]-ML-D2	SS-III-30 [780-980+AL]	QU-[W]-VC-SX
M0000007182	SS-III-30 [1060-1080] V3	QU-[W2A]-ML-D2	SS-IV-30 [1060-1080] V3	QU-[W2A]-VC-SX
M0000007603	SS-III-30 [AG]	QU-[W]-ML-D2	no successor product	
M0000008411	SS-III-30 [900-1100+AL]	QU-[W2AL]-ML-D1	no successor product	
SUPERSCAN IIIK-50			Successor product	
M0000006967	SS-IIIK-50 [C]	SC-[NL]-ML-D2	no successor product	
M0000009158	SS-IIIK-50 [C]	SC-[N]-ML-D2	no successor product	

Timeline for discontinuance:

End Of Life (EOL)	31/07/2022	Effective date of discontinuance
Last Time Buy (LTB)	30/07/2023	Last possible order date
Last Time Delivery (LTD)	31/12/2023	Last possible delivery date
End of Service (EOS)	30/07/2028	End of service and repairs

Additional information:

The products listed above are the main standard products only. All related options and non-standard products of the series specified above will similarly be discontinued.

As we cannot promise to repair the products until the EOL date due to component availability, we reserve the right to offer replacement products instead. These may differ in color, design and technical data from the discontinued product.



Action required on the part of the customer

RAYLASE GmbH will accept orders from customers for the specified EOL products until the LTB date. Orders cannot be cancelled. Orders will not be accepted after the LTB date. Delivery may be scheduled with various delivery times up until the LTD date. No deliveries will be made after the LTD date.

End of Service (EOS)

End of servicing and maintenance for these products. Replacement parts will no longer be available. In most cases, we will try to carry out a repair, but this cannot always be guaranteed!

We would like to express our thanks in advance for your understanding in relation to this product discontinuance.

If you have any questions, please don't hesitate to contact us.

Kind regards

Wolfgang Lehmann
Head of Product Management
RAYLASE GmbH